Ottawa County Real Estate Evaluations

From 1984-2019


Why do real estate evaluations?

Protect Public Health and Environment

- Ensure systems are functioning correctly
- Ensure buyers know what they are purchasing
- Educational opportunity on operation and maintenance

What do we evaluate

- Well construction
- Well isolation distances
- Water quality
- Tank size and construction
- Drainfield size and condition
- Drainfield isolation to water table and surface water





Address: Parcel:

Date: 11/20/19

EH Specialist: Matt Allen



Holland, Mi 49424 (616) 393-5645 Fax (616) 393-5643

0 Feet 17.21 34.4

What do we find

Well corrections last three years

- 40- buried well heads
- 23- water results over MCL
- 57- well to close to septic components
- 60- improperly abandoned wells
- 130- Well construction issues

SDS corrections last three years


- 25- direct discharges to ditch- 1.8mg
- 24- could not locate a system- 1.75mg
- 7- systems installed on wrong property
- 59-systems installed in the water table4.3mg
- 63- undersized systems
- 54- systems full of sludge













Feb. 15, 1996

Dear Sir Please put a rush on this. Mr. Smith went out last Saturday morning to check a spot that was spen in our back yard and the ground that he was standing on went down with him into the septic truk he went. We almost lost him. no B/P no temp. I do have it covered with a strip of tin and a house door and the police tape is still there. Just half of the cover broke and fell in side.

Thank You

Mr. E Mrs. Smith

Matthew Allen
Environmental Health Supervisor
mallen@miottawa.org